

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-009309**Date Inspected:** 11-Sep-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	Chen Ying Xin, Ma Yun, Liu Xiaocui			CWI Present:	Yes	No
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No N/A
				Delayed / Cancelled:	Yes	No N/A
Bridge No:	34-0006			Component:	Tower	

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

Bay 10 North Tower Lift 3 CD corner seam

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% and Visual Testing (VT) of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT reports for this date. The members are identified as Tower Components. The weld designations reviewed are as follows.

NSTL3-3B/K-81B Green Tag No. 9836

Bay 10 North Tower Lift 4 skin A Doubler Plate

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% and Visual Testing (VT) of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT reports for this date. The members are identified as Tower Components. The weld designations reviewed are as follows.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

NSD1-FASA4-1B/E-4-18, 19, 20, 21, 26

NSD1-FASA4-1C/E-1, 2, 3, 4, 16

This Quality Assurance (QA) Inspector observed the following work in progress:

Bay 10

STRUT PLATE

SMAW welding of weld joint 11A located on ND1-A6002-6.

Welder is identified as 053049. ZPMC QC is identified as Mr. Ma Yun.

The welding variables recorded by QC appeared to comply with WPS-B-T-2212-Tc-U5b.

SMAW welding of weld joint 12A located on ED1-A6003-4.

Welder is identified as 053050. ZPMC QC is identified as Mr. Ma Yun.

The welding variables recorded by QC appeared to comply with WPS-B-T-2212-Tc-U5b.

SMAW welding of weld joint 10B located on ND1-A6002-10.

Welder is identified as 052793. ZPMC QC is identified as Mr. Yu Zhi Lai.

The welding variables recorded by QC appeared to comply with WPS-B-T-3212-Tc-U5b-1.

SMAW welding of weld joint 27 located on ED1-A6003-2.

Welder is identified as 040268. ZPMC QC is identified as Mr. Yu Zhi Lai.

The welding variables recorded by QC appeared to comply with WPS-B-T-2112.

SOUTH TOWER INTERIOR SPLICE PLATE

FCAW welding of weld joint 2B located on SSD1-SPSA3-70.

Welder is identified as 053870. ZPMC QC is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-2231-Tc-U5-F-1.

Bay 11

EAST TOWER LIFT3 CORNER DIAGONAL PLATE

FCAW welding of weld joint 79 located on ESTL3-4B/K.

Welder is identified as 068865. ZPMC QC is identified as Mr. Liu Xiao Zhong.

The welding variables recorded by QC appeared to comply with WPS-B-T-2232-Tc-P4-F-2.

FCAW welding of weld joint 78 located on ESTL3-4B/K.

Welder is identified as 066897. ZPMC QC is identified as Mr. Liu Xiao Zhong.

The welding variables recorded by QC appeared to comply with WPS-B-T-2231-Tc-P4-F-2.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Jim Simonis - 134-7246-3441, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Umesh
----------------------	---------------

Quality Assurance Inspector

Reviewed By:	Clifford,William
---------------------	------------------

QA Reviewer
